ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W1801, W1803, W1074	3rd Crs, NA	MCHS LAYOUT
Segment No.	**Total Length (m)**	
5/C-W1801/S123627	200.78	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	87.64	77.612675	13.073384	77.612759	13.072596	W1093	W1076
2	113.14	77.613564	13.073411	77.613665	13.072393	W1074	W1801

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Graveyard Burial building at Jakkur village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	1500000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of Graveyard Burial building at Jakkur village in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	005-16-000005
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/E-PMT/190/2015-16	03/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
03/02/2016	02/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRISHNA REDDY		0.00
Phone No.	**E-Mail ID**	
9448294632		

Field Inspection Details

Number of Trees

5

Any Other Information

Name

Chandrakanth

Date of Inspection

09/06/2016

Remarks

completed

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1801, W1803, W1074

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	09/06/2016	09/07/2016	COMPLETED
SE	VASU K M	09/06/2016	09/07/2016	COMPLETED
EE	YARAPPA REDDY	09/06/2016	09/07/2016	COMPLETED
AEE	J N LOKESH	09/06/2016	09/07/2016	COMPLETED
AE	CHANDRAKANTH	09/06/2016	09/07/2016	COMPLETED
AE	CHANDRAKANTH	09/06/2016	09/07/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W1801, W1803, W1074